





TOUGH WORKING COMFORT

AS361C SALUS

EN ISO 20345:2022
S7S SC LG FO M HRO SR

RHEON™



AS361C SALUS

EN ISO 20345:2022
S7S SC LG FO M HRO SR

The AS361C 8" ankle-high safety boot with side zip features the game-changing RHEON™ metatarsal protection. This new RHEON™ material protects the metatarsal bones in the foot by dynamically responding to and absorbing the energy from any impact. The advantage of RHEON™ over traditional metatarsal protection is that it is lightweight and ultra-thin, to maximise user comfort, and retain the aesthetics of the boot design. The RHEON™ material is certified to EN ISO 20345:2022+A1:2024 and exceeds the minimum clearance after impact on testing. The AS361C SALUS named after the Roman Goddess of Safety, offers all day long support and protection.

SIZE: 6-13 (including 6.5 and 10.5)

SKU: 44909-84254

COLOUR: Black

OUTSOLE MATERIAL: Rubber

WEIGHT: 865g (Half size UK 8)

SAFETY ICONS



SAFETY ICON KEY

Water Resistant	Toe Cap	Ladder Grip	Heat Resistant	Shock-absorbing Heel	Cold Insulation
Waterproof	Composite Toe Cap	Side Zip	Antistatic	Memory Foam Footbed	Metatarsal Protection
Midsole	Composite Midsole	Oil Resistant	Electro-static Dissipative	Metal Free	Scuff Cap

FEATURES

- RHEON Metatarsal Protection
- Internal Waterproof Membrane
- Heavy Moulded Rubber Toe Guard for Extra Durability Tested to New Scuff Cap Standard (SC)
- Heavy Moulded Rubber Heel Counter for Enhanced Heel Support and Extra Protection
- Deep Padded Mesh Collar for Extra Comfort
- Comfortable, Cushioned and Removable PU Footbed with Arch Support
- Phylon Midsole Enhances Comfort and Shock Absorption
- Deep Cleated Rubber Outsole
- Performance Ladder Grip on Outsole Tested to New Ladder Grip Standard (LG)

PRODUCT CARE

To enhance the life & performance of the footwear, upper should be kept clean & dry. Dry/damp cloth or shoe polish/spray to be used as per the need. Sole to be checked and clean regularly to maintain its traction. Any obvious damage in footwear may reduce full protection and must be replaced.